


DPVR AIO GO Instructions for Use

1. Run DPVR AIO GO Setup.exe on Windows 10 to install
2. Run DPVR AIO GO, the following interface will be displayed when the device is not connected



3. Use the USB data cable to connect the PC and the VR all-in-one device. After the connection is successful, the corresponding model device will be displayed



4. Click the corresponding icon on the interface and follow the instructions to use the corresponding function